

Please be advised that the Hour Meter installed on all future dehumidifiers built by OASIS will have a physically different appearance as shown in the images below.

This change is being introduced as a result of a change in the component specification introduced by our supplier.



ORIGINAL Part



NEW Part